



0000014

EPA Region 5 Records Ctr.



200859

January 15, 1998

Ababi Harris
U.S. EPA Region V
77 West Jackson Boulevard, SR-6J
Chicago, Illinois 60604-3590

RE: Site Security Establishment

Dear Mr. Harris:

This letter is concerning remobilization of ENTACT associates to the Master Metals site in Cleveland, Ohio on January 8, 1998 and January 9, 1998 for the purpose of establishing site security. Questions were raised as to the integrity of the perimeter fence and the danger of the open cavities still present on site.

As part of this remobilization effort the following activities were performed

- Repairing of perimeter fence
- Securing of the on site office building to prevent unauthorized entry
- Marking of all below grade sumps to prevent accidental ingress and possible injury
- Securing roundhouse structure to prevent unauthorized entry (including below grade sumps)
- Marking of excavated cavities to prevent accidental ingress and possible injury

Attached is a photographic record of the pertinent actions taken in regard to site access. Before departing the site, ENTACT associates secured the entry gates to prevent vehicular traffic and the repairs performed on the perimeter fence will prevent any entry by human or animals.

If you have any questions or comments regarding this matter, please feel free to contact myself at (630) 616-2100.

Respectfully,


Shane D. Banks
ENTACT, Inc.

Enclosures



Chicago Office

1360 North Wood Dale Road Suite A • Wood Dale IL 60191 • 630 616 2100 • Fax 630 616 9203


Chicago • Dallas • Indianapolis



Perimeter Fence Repair



Perimeter Fence Repair



Perimeter Fence Repair




Office Building



Below Grade Sumps




Below Grade Sumps





Below Grade Sumps



Excavated Kettle Areas



Roundhouse Building (including sumps)



Roundhouse Building (including sumps)



Excavated Kettle Areas